BLACKPAD REVISITED

M. Simard-Normandin, C. Banks MuAnalysis Ottawa, Ontario, Canada martine@muanalysis.com

ABSTRACT

Since the implementation of lead-free soldering, solderability issues appear to have become more common. The higher soldering temperature releases volatiles creating solder voids. The higher temperature also increases board and component flexing. Surface mount components fall off boards and BGA (Ball Grid Array) balls crack cleanly at the intermetallic interface creating open circuits. Black pad is often found as the root cause of these issues. However, black pad is a catch-all expression used to describe a variety of problems. As common as it is, black pad is not always recognised. What does it look like? How can one differentiate black pad from other soldering defects? We present high resolution optical and SEM (Scanning Electron Microscopy) images of real-life soldering problems, demonstrating the difference between black pad issues, flexing issues and component issues, pointing at specific features identifying the syndrome.


Key words: Blackpad, solderability, solder cracks

INTRODUCTION

There are solderability issues that you can see and inspect, and there are some that are hidden from view, under components. Visible problems include tombstoning of small components, missing components, shorted pins or lifted pins in gull wing components. BGAs and QFNs (Quad Flat No leads) hide their soldering issues quite well requiring X-Ray inspection. Shorts are relatively easy to detect but open pads in QFNs and cracked balls or head on pillow balls in BGAs are not always detectable. In twodimensional X-Ray, there are often components of the other side of the card that can hide the region of interest.

FINDING HIDDEN DEFECTS

Many techniques are available, each with strengths and weaknesses. X-Ray imaging detects solder bridges, missing solder, voids, but is not so good at detecting cracked solder, as explained in Figure 1. Acoustic microscopy detects delamination inside a component and bowing but cannot see a cracked BGA ball because the BGA substrate has too much absorption. Failure analysis techniques are good at detecting excess current because that generates heat or light. When it comes to opens, since there is no signal, there is no tell tale signature. One needs to resort to electrical tests for continuity if possible, do Dye and Pry or cross-sections, which are both destructive. SQUID (Superconducting Quantum Interference Device) analysis is very expensive and quite difficult to interpret.






Figure 1. Why are BGA cracks so hard to see? a) Crosssection optical image of a ball separated on the board side. The viewing direction for optical microscopy (before cross-section) is indicated by the arrow. Along the edge of the package, the solder wraps around the edge of the solder pad hiding the crack from view. b) Cross-section SEM image of a ball separated on the component side. Even if optical inspection had been possible, the crack is hidden by the solder mask. Encapsulation epoxy has been used to prepare these parts for cross-section. The epoxy expands during curing opening up existing cracks. Before encapsulation the cracks were most likely closed, remaining hidden to X-Ray examination.

WHAT IS BLACKPAD

Black pad is a corrosion of the surface of the Ni layer during gold plating in ENIG (Electroless Nickel Immersion Gold)¹. This causes the growth of a thin Ni₃P layer which prevents the formation of the intermetallic layer during soldering. The consequences are poor wetting and a weak solder joint. The corrosion can be uneven across the board, with areas more affected than others. Blackpad is recognised before soldering or on pads with separated solder joints by characteristic mud cracks visible in SEM imaging or by cross-sections and high magnification imaging.





Figure 2. Cross-section of solder pad affected with blackpad. The Ni_3P layer is less than a micrometre thick and shows cracks.

Blackpad is often detected as a root cause after assembly when failures occur. Yet there is no need to wait for "autopsy" before the diagnostic of a "disease" is done. The characteristic signature of blackpad is visible on a bare board. Although boards with blackpad cannot be "cured", they can be removed, avoiding the expense of an assembly doomed to failure.

BLACKPAD ON BARE BOARDS

In extreme cases blackpad gives a dark appearance to solder pads, hence its name. When exposed to a humid environment the nickel corrosion can progress and cause blistering on the pads as shown in Figure 3.






Figure 3. Blackpad affected board exposed to humidity. a) optical cross-section image across a blister bubble. b) Planview SEM image of another region of the same part. The mud cracks are very visible in SEM because they are coated with the ENIG gold plating layer. They are also visible in the optical cross-section, once one is acquainted with their appearance. The blue arrow in (a) points to such a crack. A few more are visible if you look carefully.

The main issue with optical microscopy is the lack of depth of field at high magnification. A small tilt or curvature of the sample and focus is lost. It has the advantage, on the other hand, of showing colors. In SEM imaging, there is very poor contrast between Cu and Ni, but depth of field is not an issue. Mud cracks do show well as seen in Figure 4, but they are very small and can be missed if one does not know what to look for.




Figure 4. SEM cross-section image of a board affected by blackpad. A string of mud cracks is visible at the interface between the gold layer and the nickel. They have the appearance of little black dots at this magnification.

BLACKPAD AFTER SOLDER

When small components fall off a board at the slightest touch, the culprit is often blackpad. In the example shown in Figure 5, there is very poor wetting of the solder on the pad under the capacitor, and where the capacitor has fallen off, there is no solder left on the pad. X-Ray imaging of the pads of fallen components is a rapid way to check if blackpad is involved.





Figure 5. Left: X-Ray image showing poor solder wetting of a tantalum capacitor. Right: area where the capacitor has fallen. Most of the area of the pads is clear of solder.

When a part falls off, one is not tempted to take an X-Ray of the region, yet it may provide valuable information on the failure mechanism if the path is clear of interference from components on the other side.

BGAs do not usually fall off and when cracked balls are suspected. Dye and Pry is a common technique to assess the number of bad balls. Detailed examination of the failed solder pads will indicate whether the problem was blackpad or some other mechanism. An example is shown in Figure 6.



c)

Figure 6. a) SEM image of a board pad after Dye and Pry test. Approximately half of the pad is covered with dye (darker region). The rest of the dye adhered to the solder ball during the pry. b) SEM image of the partially dyed

solder ball remaining on the component after Dye and Pry. c) Higher magnification image of the light region on the board pad.

Mud cracks are present overall and there are small clumps approximately $10\mu m$ across (red arrow, Figure 6c). These are small regions of intermetallic formation. EDX (Energy Dispersive X-Ray) analysis of the mud crack region reveals a high level of phosphorus, attributed to the formation of the Ni₃P layer at the nickel surface.

In solder joint cross-sections, in addition to mud cracks, one sees that the intermetallic layer is not uniform in parts affected by blackpad. See Figure 7.





Figure 7. SEM cross-section images of a) a good board and b) a board affected by blackpad. On the bad board, the intermetallic layer is not continuous and the mud crack affected Ni_3P layer has formed on top of the nickel.

Note that the SEM images in Figure 7 were taken with a 20kV acceleration voltage, and that of Figure 2 was taken at 5kV. Hence the appearance of the layers is different.

One does not need an electron microscope to confirm back pad, optical images of the same parts as in Figure 7 are shown in Figure 8.



b)

Figure 8. Optical images corresponding to the SEM images in Figure 7. There is no intermetallic layer on the bad board.

OTHER SOLDER FAILURES

Blackpad is not the only mechanism causing solder cracks and one needs to recognise the morphological signature of the root cause.

Board flexion can also cause cracks, and such cracks are often found at opposite sides of the ball. They are usually very sharp, following grain boundaries and occur in or near the intermetallic.




Figure 9. Example of a flexion crack in a BGA ball.

CTE (Coefficient of Thermal Expansion) fatigue also causes solder cracks but they have a different morphology. The cyclical heating and cooling of the part causes phase separation in the solder, creating a weaker area where the crack occurs.








Figure 10. Examples of a CTE solder cracking event. The various phases of the solder have separated creating weak areas. a) Optical image showing the contrast of the different phases. The solder has started cracking on the right. b) SEM image of a nearby pin where the crack has propagated.

CONCLUSION

Blackpad is a common source of solder failures. It has a distinct morphology, recognizable before soldering and in cross-section imaging before or after soldering. Proper inspection of boards and cross-sections of coupons can alleviate the problem by scrapping affected parts before assembly, reducing waste of components and expensive reruns. It must not be confused with other mechanisms causing solder cracks. They have other characteristic signatures.

REFERENCES

[1] K. Zeng, R. Stierman, D. Abbott, and M. Murtuza, "The Root Cause of Black Pad Failure of Solder Joints with Electroless Ni/Immersion Gold Plating", <u>The Journal</u> <u>of The Minerals, Metals & Materials Society (JOM)</u>, June 2006, pp75.