



KE-2050/KE-2060 Causes and countermeasures of patch failure:

- 一.Patch offset
- 二.Uneven patches throughout the substrate (each substrate is offset in a different way)
- 三.Only part of the substrate is offset.
- 四.Only certain components are offset.
- 五.The patch Angle is offset.
- 六.Component absorption error.
- 七.Laser identification (component identification) error.
- 八.Nozzle loading and unloading error.
- 九.Mark (BOC mark, IC mark) identification error.
- 十.Image recognition error (KE-2060 only).
- 十一.Analysis of the main reasons for throwing material.