

Inspection Result View [ 20171116112954 ] Total Ready Count : 0

[Defect Information] M0 / R R81 / W 3 / F 14 / Window Type - Mounting inspector / Misalign SMT / Result - Defect

Defect

start Mirtec Inspector 4.5... Data Server (AOI) (6...

11:31 AM

Misalign SMT  
Wrong part SMT  
Missing part SMT  
Wrong polarity SMT  
Tombstone SMT  
Insufficient solder SMT  
Open solder SMT  
Bridging SMT  
Excessive solder SMT  
Damaged part SMT  
Flip Part SMT  
Wrong Label  
Missing Label  
Cold Solder SMT  
Lifted/Bent Lead SMT  
Dropped part SMT  
Over heat SMT  
Contaminated Part  
Missing solder SMT  
Extra part SMT

Ref. ID	Part Number	M	F	W	Defect Type
D48	P03798	0	15	1	Missing
R61	CRCW08054532FX	0	14	3	Missing
R180	P20166	0	6	2	Missing
R60	CRCW08051001FX	0	13	2	InSufSolder
R127	P04153	0	5	3	Missing
R153	P04154	0	4	2	Missing
R150	P04154	0	3	2	Missing
R149	P04154	0	3	2	Missing
R164	P04154	0	3	2	Missing
D39	P03798	0	8	1	Missing

Review Close