

Persang Alloy Industries X ray 6600 for PCB

[Persang Alloy Industries Pvt. Ltd.](#) (PAI) is one of India's largest manufacturers / exporter of solders, soldering chemicals and alloys. Based in Vadodara, Customers include Sony, HP, Siemens, Asus, Foxconn and so on, with high recognition since 1989.

[PAI](#) manufactures a wide variety of solders, lead free alloys and fluxes in various forms which perform critical tasks in the electronic, electrical and automobile industries.

Persang Alloy Industries X ray 6600



The most common problem with solder paste/solder is the inclusion of impurities, which is very detrimental to the soldering effect. This is a special concern for solder paste manufacturers. The solder paste contains impurities, which will not only affect the soldering effect but also affect the customer's experience with the product.

Thanks to the manufacturer – PAI for being responsible for products quality, let us experience good product quality.

Family of [Industrial X-ray inspection machine](#) & [BGA rework station](#)

Last Article: [Method for detecting electronic components quickly](#)

Next Article: [Formation and prevention of SMT BGA voids](#)

Hot: [The Reason for BGA insufficient solder & short](#)

Maybe you still are interested in: [Solder paste printing defects and solutions in SMT chip processing process](#)

[Advantages of X-ray SMD counter](#)

[The difference between the detection equipment AOI & X-RAY](#)