



Seamark Technology Group (H.K.) CO., LTD

Add: Building 10, Huaide Cuihai Industrial Park, Fuyong Street, Bao'an, Shenzhen

www.seamarkxray.com

Tel: 86-755-29929955

Fax: 86-755-29929953

E-mail: sales25@zhuomao.com.cn

Skyworth Group pay attention to products quality inspection

Founded in 1988, [Skyworth Group Co., Ltd.](#) is mainly engaged in multimedia (smart TV, content operation business), smart appliances (refrigerators, washing machines, air conditioners, kitchen appliances, etc.), intelligent system technology, modern services. Industry and other four major businesses, the group has Skyworth Group (H00751) and Skyworth Digital (000810) two listed companies, several high-tech enterprises, with state-level enterprise technology center, national industrial design center, is "Made in China 2025". The first batch of demonstration units have been among the top 100 Chinese electronics companies for many years.

Skyworth Group Co., Ltd Pay Attention to product quality and brand image all the time.

Under the continuous wave of new technology, Skyworth has introduced automatic production lines and quality testing equipment to improve the pass rate and achieve excellence.



Seamark Technology Group (H.K.) CO., LTD


Add: Building 10, Huaide Cuihai Industrial Park, Fuyong Street, Bao'an, Shenzhen

www.seamarkxray.com

Tel: 86-755-29929955

Fax: 86-755-29929953

E-mail: sales25@zhuomao.com.cn



Skyworth Group pay attention to products quality inspection

X-RAY inspection equipment is a non-destructive testing equipment. It does not need to open the product for testing. The x-ray directly penetrates the inside of the sample, maps the result graph inside the sample, and analyzes whether the product has defective defects according to the pattern.

X-RAY can detect internal cracks in components, Defects, BGA repair testing, etc. It is very meaningful to judge the virtual welding, false welding, shifting, etc.

Family of Industrial X-ray inspection machine & BGA rework station

Last Article: [SMT BGA solder ball inspection method](#)

Next Article: [Formation and prevention of SMT BGA voids](#)

Hot: [The Reason for BGA insufficient solder & short](#)



Seamark Technology Group (H.K.) CO., LTD

Add: Building10, Huaide Cuihai Industrial Park, Fuyong Street, Bao'an, Shenzhen

www.seamarkxray.com

Tel: 86-755-29929955

Fax: 86-755-29929953

E-mail: sales25@zhuomao.com.cn

Maybe you still are interested in: [Solder paste printing defects and solutions in SMT chip processing process](#)

[Highest Quality levels Tool X-ray for industries-SMT/batteries/ceramic/Electronic /semiconductor;](#)

[The difference between the detection equipment AOI & X-RAY](#)